

Gabriel HD

THE ORIGINAL



FLEETLINE®

Heavy Duty Commercial Vehicle Shock Absorbers

FOR **FREIGHTLINER®**

DTNA Part #	Part Description	Position	FleetLine® Part #	Alliance Gas Part #	Alliance Hydraulic Part #
16-18708-000	FAS II Airliner Air Suspension	Rear	85724	ABP N32 G900001	ABP N32 O900001
18-41762-000	Models with 72" High-Roof Sleeper and 1/2" Top mounting bolt	Cab	83038	ABP N32 G900012	ABP N32 O900012
10-13809-000	Models with 12K to 14.6K Taper-leaf Suspension	Front	85958	ABP N32 G900077	ABP N32 O900077
16-14759-000	Models with O.E.M. Interchange 16-14759-000	Front / Rear	85000	ABP N32 G900028	ABP N32 O900028
10-13634-000	Models with 12K to 13.3K lb Taper-leaf Suspension	Front	85918	ABP N32 G900003	ABP N32 O900003
10-14317-000	Cascadia models with 12K to 13.3K lb Taper-leaf Suspension	Front	83396	ABP N32 G900091	ABP N32 O900091
10-13760-000	M2 106 & 108SD Models with 8K to 16K lb Taper-leaf Spring	Front	85959		ABP N32 O900084
16-008-031	International / Prostar models with Day Cab and 12,000-14,000 lb Taperleaf Front Spring Suspension. Models with Sleeper cab and 12,350 lb Leaf Spring Suspension, 8600 Models with Taperleaf Front Spring Suspension	Front	85954	ABP N32 G900044	ABP N32 O900044
18-32999-000	Freightliner Century Class Cab Shocks	Cab	83001	ABP N32 G900008	ABP N32 O900008
016-003-016	Models with Neway Tag Axle Air Suspension	Rear	83128	ABP N32 G900015	ABP N32 O900015
10-12032-002	FLA / FLB / FLC / FLD	Front	85320	ABP N32 G900004	ABP N32 O900004
016-007-013	Cement Trucks with 3/4" Bushing and Sleeve Mount	Front / Rear	646155		ABP N32 O900029
10-12390-000	(2002 - 08) Models with 10K to 12K lb Taper-leaf Suspension	Front	85920	ABP N32 G900081	ABP N32 O900081
016-006-001	Volvo, Mack, Renegade RV Models with 38,000 lb and 40,000lb Rear Air Suspension	Rear	85088	ABP N32 G900078	ABP N32 O900078
16725-01	Models with Reyco 79KB Rear Steel Spring Suspension	Rear	83126	ABP N32 G900056	ABP N32 O900056

All product and company names are trademarks™ or registered® trademarks of their respective holders. Use of them does not imply any affiliation with or endorsement by them. Freightliner Trucks is a division of Daimler Truck North America LLC and not owned or affiliated with Gabriel (Ride Control, LLC).

Form # 124D720A



See how Gabriel® FleetLine® outperforms the competition!
AnswerGarage.com/FleetLineAdvantages

Gabriel HD
 THE ORIGINAL

Gabriel.com

**RUN LONGER,
 RUN STRONGER**

CHECK YOUR SHOCKS!



Leaking



Upper or lower
mount broken



Upper or lower
bushing torn



Broken internally
or jammed in
collapsed position



Improper
installation



Dust tube
torn



Truck mount
failure



Bent or
dented



Visual Inspections AREN'T ENOUGH!



SCAN TO WATCH
the Gabriel®
Heat Test

Above are the visual signs of shock failure but when a shock has failed internally, it is **VISUALLY UNDETECTABLE**. It is a good maintenance practice to perform the Gabriel® Heat Test using the **GABRIEL® SHOCK ABSORBER TESTER**.



Get your Gabriel®
Shock Tester today!

New Gabriel® Shocks give you:

- ✓ Maximum tire & air spring life
- ✓ Driver comfort & retention
- ✓ Safer braking & handling

SCAN TO
WATCH



How to tell if your HD
shocks are worn

Gabriel HD

THE ORIGINAL

CheckYourShocks.com

