


Door Assemblies and Components

Replacement door leaf assemblies and components



Product Highlights

Feature or benefit

- Replacement door leaf assemblies and repair components.

Top Movers - Spectal

Material Number	Material Description
TBB THSP03001	DOOR END TBB DOOR LEAF
TBB THSP91015	BURGLAR STOP BLK NEW GEN/ KIT OF 50
TBB THSP04001	MOUNTING BLOCK UPPER
TBB THSP05002	CLYLINDER LOCK VANDALOCK

TBB THSP09901	AFT LEAF
TBB THSP09903	FORWARD LEAF WITH VANDALOCK
TBB THSP09900	FORWARD LEAF W/O VANDALOCK
TBB THSP02002	HINGE BLOCK UPPER TBB DOOR LEAF
TBB THSP83074	FRAME KIT
TBB THSP06002	ROD GUIDE VANDALOCK

Warranty Information

The warranty period is 1 Year from date of purchase/unlimited mileage

Last updated: Friday, 28 July 2023 03:02 PM

[^Back to Top](#)

Copyright © Daimler Truck North America LLC. [Privacy Statement](#), [Legal Notices and Terms](#)
(<https://northamerica.daimlertruck.com/privacy-policy>). [Privacy Settings](#)
All rights reserved. Daimler Truck North America LLC is a Daimler company.